
## WIRING INSTRUCTIONS

## TITLE REVERSING LARGE DRILLS (TRIPLE REDUCTION)

BULLETIN 58-01-0566



WIRING SPECIFICATIONS						
Wire No.	Wire Color	Origin or Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation.		
1	Black	Cord	3-1/4"	Strip 3/8" & tin		
2	White	Cord	3-1/4"	Strip 3/8" & tin		
3	Green	Cord	10"	Strip 3/16" for T1		
4	Black	Field	7-1/2;"	Strip 1/4" for C1		
5	Yellow	Field	7-1/2"	Strip 1/4" for C1		
6	Red			——————————————————————————————————————		
7	Black			Strip 1/4" for C1		
8	Yellow			→ Strip 1/4" for C1		
9	White	16	. 8"	Strip 3/8" solder / Strip 1/4" for C1		
10	Red	16	8"	Strip 3/8" solder / Strip 1/4" for C1		
11	White	16	8''	Strip 3/8" & tin / Strip 1/4" for C1		

## NOTE: All leads must be held to ± 1/8". All field leads to be measured from and perpendicular to laminations. All lead lengths are before stripping.

TERMINAL DESCRIPTION						
Code	Code Part No.					
T1	23-74-0390	1				
CONNECTOR DESCRIPTION						
Code	Part No.	Qnty.				
C1	23-74-0360	4				