SPX Corporation 5885 11th Street Rockford, IL 61109-3699 USA

Internet Address: http://www.powerteam.com Tech. Services: (800) 477-8326 Fax: (800) 765-8326 Order Entry: (800) 541-1418 Fax: (800) 288-7031

SPX Corporation 655 Eisenhower Drive Owatonna, MN 55060-0995 USA Phone: (507) 455-7000 Tech. Services: (800) 533-6127

Fax: (800) 955-8329 Order Entry: (507) 455-1480 Fax: (800) 283-8665 International Sales: (507) 455-7223

Fax: (507) 455-7746

Form No. 101342

Parts List for:

51684 **RD1506**


RD1506-VLCEK RD15013

RD15013-VLCEK

MODEL B DOUBLE-ACTING HYDRAULIC CYLINDER

Max. Capacity: 153.4 Tons at 10,000 PSI







■ In the event that the cylinder retract port is ever restricted or plugged, a double-acting cylinder relief valve will help prevent excessive pressure from building in the cylinder. DO NOT attempt to adjust or service this relief valve! If oil leakage is detected from this relief valve, discontinue use of the cylinder immediately and contact Power Team or OTC Technical Services. Only Power Team or OTC Authorized Hydraulic Service Centers should service this relief valve.

Item	Part	No.	
No.	No.	Req'd	Description
1	421939OR9	1	Cylinder Lift Handle Assembly
			(For RD1506, RD1506-VLCEK, RD15013 & RD15013-VLCEK)
2	51313	1	Piston Rod (For RD1506 & RD1506-VLCEK)
	51314	1	Piston Rod (For 51684, RD15013 & RD15013-VLCEK)
3	51312	1	Retainer Nut (Torque to 90/110 ft. lbs.)
4	*13425	1	O-ring (6-1/4 x 6" x 1/8)
5	*19298	1	Backup Washer (6-1/4 x 6" x .048)
6	*19293	1	U-cup
7	*19349	1	Backup Washer (5" x 4-1/2 x .105)
8	*207497	1	Rod Wiper
9	38425	1	Serrated Insert (For 51684, RD1506 & RD15013)
	350582	1	Load Cap (For RD1506-VLCEK & RD15013-VLCEK)
10	17816	1	Cap Screw (3/8-16 UNC X 3" Lg.;
	*****		For 51684, RD1506 & RD15013)
11	*19295	1	O-ring (2-1/2 x 2-1/4 x 1/8)
12	*19296	1	Piston T-seal w/ Backup Rings
13	51311	1	Piston Head (Use Loctite No. 277 when assembling Piston Head to Piston Rod [Item #2]. Torque to 200 ft. lbs.)
14	64455	1	Cylinder Body (For RD1506 & RD1506-VLCEK)
	64448	1	Cylinder Body (For 51684, RD15013 & RD15013-VLCEK)
16	9796	2	Ram Half Coupler w/ Plastic Dust Cap
			(For RD1506, RD1506-VLCEK, RD15013 & RD15013-VLCEK)
15	10469	1	Fitting (For 51684)
17	10648	1	Fitting (For 51684)
PARTS INCLUDED BUT NOT SHOWN Drawing			
	37782	1	Warning Decal
	350718	1	Trade Name Decal (For RD1506 & RD1506-VLCEK)
	350719	1	Trade Name Decal (For RD15013 & RD15013-VLCEK)
	421271	1	Thread Protector (For RD1506 & RD15013)

Part numbers marked with an asterisk (*) are contained in Repair Kit No. 300007.

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. **Therefore: Use only genuine replacement parts!**

Additional questions can be directed to our Technical Services Department.

Note: Shaded areas reflect last revision(s) made to this form.