


R42

Stub Drill



General Purpose



d1 R letter	d1 decimal Inch	l2 Inch	l1 Inch	e-code	USD
A	0.2340	1.5/16	2.7/16	R42A	6.17
B	0.2380	1.3/8	2.1/2	R42B	6.17
C	0.2420	1.3/8	2.1/2	R42C	6.17
D	0.2460	1.3/8	2.1/2	R42D	6.17
E	0.2500	1.3/8	2.1/2	R42E	5.53
F	0.2570	1.7/16	2.5/8	R42F	6.68
G	0.2610	1.7/16	2.5/8	R42G	7.12
H	0.2660	1.1/2	2.11/16	R42H	7.12
I	0.2720	1.1/2	2.11/16	R42I	7.12
J	0.2770	1.1/2	2.11/16	R42J	7.70
K	0.2810	1.1/2	2.11/16	R42K	8.21
L	0.2900	1.9/16	2.3/4	R42L	8.21
M	0.2950	1.9/16	2.3/4	R42M	8.99
N	0.3020	1.5/8	2.13/16	R42N	8.99
O	0.3160	1.11/16	2.15/16	R42O	9.23
P	0.3230	1.11/16	2.15/16	R42P	10.15
Q	0.3320	1.11/16	3"	R42Q	10.15
R	0.3390	1.11/16	3"	R42R	10.15
S	0.3480	1.3/4	3.1/16	R42S	11.75
T	0.3580	1.3/4	3.1/16	R42T	13.65
U	0.3680	1.13/16	3.1/8	R42U	13.65
V	0.3770	1.7/8	3.1/4	R42V	14.35
W	0.3860	1.7/8	3.1/4	R42W	15.20
X	0.3970	1.15/16	3.5/16	R42X	17.60
Y	0.4040	1.15/16	3.5/16	R42Y	20.95



d ₁ R letter	d ₁ decimal Inch	l ₂ Inch	l ₁ Inch	e-code	USD
Z	0.4130	2"	3.3/8	R42Z	20.95